


- Change this value using the + and - buttons.
- Press the M button. The day display (top left in the display) will flash as a number.
- Change this value using the + and - buttons. Use 1 for Monday, 2 for Tuesday, 3 for Wednesday, 4 for Thursday, 5 for Friday, 6 for Saturday and 7 for Sunday.

## Temp. Calibration & IP Address Setting


Temp. Calibration: Turn thermostat off, then press M button for 3 sec. to calibrate Temp. by pressing "+" and "-" buttons.

Range: -8°C ~ 8°C

## Wiring Diagram



## Dimensions



## Installation

